



DC-5000

DUST COLLECTOR

10001058T

~400V, 50Hz/3

PARTS LIST

JPW (TOOL) AG

Tämperlistrasse 5

CH-8117 Fällanden

Switzerland

Phone +41 44 806 47 48


Fax +41 44 806 47 58

www.jettools.com

P-**10001058 T**

2016-08

Parts Breakdown for DC-5000 Dust Collector



Parts List for DC-5000 Dust Collector

Index No.	Part No.	Description	Size	Qty.
1	DC5000-001	Collector Bag	Ø500x1100	4
2	DC5000-002	Bag Clamp		8
3	DC5000-003	Spring for Bag Clamp		8
4	DC5000-004	Collector		4
5	DC5000-005	Hex Bolt	M8x16	16
6	DC5000-006	Flat Washer	8	16
7	DC5000-007	Middle bag Support		4
8	DC5000-008	Filter Bag		4
9	DC5000-009	Upper bag Support		4
10	DC5000-010	Inlet Port		1
11	DC5000-011	Inlet Guard		1
12	DC5000-012	Pan Head Screw	M6x12	12
13	DC5000-013	Packing		1
14	DC5000-014	Cap Screw	M6x20-L	1
15	DC5000-015	Washer		1
16	DC5000-016	Impeller		1
17	DC5000-017	Hex Bolt	M10x20	4
18	DC5000-018	Lock Washer	10	8
19	DC5000-019	Packing		4
20	DC5000-020	Impeller Housing		1
21	DC5000-021	Hex. Nut	M6	10
22	DC5000-022	Flat Washer	6	36
23	DC5000-023	Hex Bolt	M6x55	8
24	DC5000-024	Washer		1
25	DC5000-025T	Motor 400V,50Hz, 3PH, P1=5.65kW complete assembly		1
	DC5000-025-1	Motor Cover(not shown)		1
	DC5000-025-2	Motor Fan(not shown)		1
	DC5000-025-3	Junction Box(not shown)		1
26	DC5000-026	Stand Support		4
27	DC5000-027	Hex Bolt	M6x10	16
28	DC5000-028	Connect Plate		4
29	DC5000-029	Caster	2"	4
30	DC5000-030	Switch Plate		1
31	DC5000-031	Hex Bolt	M6x16	2
32	DC5000-032	Switch Box Base		1
33	DC5000-033	Pan Head Screw	M4x12	4
34	DC5000-034	Packing		1
35	DC5000-035	Switch Box Cover		1
36	DC5000-036	Self-Tapping Screw	ST4.2x16	4
37	DC5000-037	Switch	400V 50Hz	1
38	DC5000-038	Self-Tapping Screw	ST4.2x10	2
39	DC5000-039	Cap		3
40	DC5000-040	Chain	150mm	3
41	DC5000-041	Link		4
42	DC5000-042	Hose Clamp	4"	2
43	DC5000-043	Hose	4"x2000	1
44	DC5000-044	Power cord		1
45	DC5000-045	Plug P551	400V 3PH	1
46	DC5000-046	Pan Head Screw	M4x10	1
47	DC5000-047	Spring Washer	4	1
48	DC5000-048	Flat Washer	4	1
49	DC5000-049	Tooth Washer	4	1
50	DC5000-050	Wire for Ground(yellow & Green)	1m	1
51	DC5000-051	Line Bank		1
52	DC5000-052	Lock Washer	6	18

Wiring Diagram for DC-5000 Dust Collector

10001058T..... ~ 400V, 50Hz

	colour of strands	Litzenfarben	couleur des cordons
BK	Black	Schwarz	Noir
WH	White	Weiß	blanc
BU	Blue	Blau	Bleu
BN	Brown	Braun	Brun
YE	Yellow	Gelb	Jaune
RD	Red	rot	rouge
GNYE	green-yellow	grün-gelb	vert-jaune

	meaning of symbol	Bedeutung der Zeichen	interprétation
M	motor	Motor	moteur
S	switch	Schalter	interrupteur
C	Condenser	Kondensator	Condensateur
OL	Overload cut-off	Überlastschuttschalter	Déclencheur surcharge

